
TELLIE channel calibration automation



Potential issues / suggestions:

- Would be better to check NHit instead of PIN, if possible
- Need safety interlock: stop firing immediately if NHit > 1000
- Is the time estimate (5 min/channel) realistic?
- · Are there any other issues one might encounter?