


cable routing

machine route zones, separation, service loops and strain relief



- No cable may cross cutter, chain, hot surface, sharp edge or solid; verify full motion/service envelope.
- Sensor routes are separate from PWM/motor/heater conductors; cross at 90 degrees only.