


safety chain

normally-closed hard cut; de-energize-to-trip



- Any open S0/S1/S2/TF removes K0 coil energy with firmware halted.
- Reset needs cause removal, physical lockout confirmation and explicit restart permission.