



- D1 SHOULD BE replaced with a jumper
- Use only TLV1117LV33 as LDO (U5), not something like AMS1117
- R4 and R5 can be omitted if no "External Power Detect" is required
- D3 is for debug purposes only, and can be omitted to save a bit of power

Sheet: /
File: zero-node-kicad.kicad_sch

Title: Zero Node

Size: A4	Date: 01.2026	Rev: 1.0
KiCad E.D.A. 9.0.7		Id: 1/1