
cents from 1.5 oct/V line
5
0
−5
−10
4
5
6
7
8
9
Frequency CV (V)
triangle
saw + square +
pulse +


Per-step CV offsets (limits clipped)
offset (cents)
20
10
0
−10
−20
20
25
30
35
40
CV step (file index)