Appendix B - Internal Moisture Intrusion Checklist

Clear

Grey Black

Perform as soon as possible after moisture intrusion problems are reported.

1 circim us soon us possible urter moistu	ie intrusion problems are reported.
Property Name: BOULEVARD	Unit# 125
Date Reported: 10/28/21	Inspector's Name: Mark Gordillo
Time Reported: 12:00 am	

Type	of moisture	intrusion	(clear, grey	z. black water)	•

Check Only One

Inspector's Initials	Comments/Follow-up
M.G.	
M.G.	
M.G.	

Inspection Item:

 $Staining/discoloration\ observed\ on\ building\ materials:$

Yes	No	Inspector's Initials	Comments/Follow-up
-----	----	----------------------	--------------------

 $Staining/discoloration\ observed\ near\ utilities:$

Yes	No	Inspector's Initials	Comments/Follow-up

Building material impacted by moisture intrusion:

Location - which room / room(s) etc.
Square Footages
Wood moisture meter results
Concrete moisture meter results

M/BEDROOM	G/BEDROOM

tannbet	~	h
IGILIDE	u	v