Appendix B - Internal Moisture Intrusion Checklist

Perform as soon as possible after moisture intrusion problems are reported.

reform as soon as possible after moistare intrasion problems are reported.		
Property Name: ARBORS	Unit# A07	
Date Reported: 06/03/22	Inspector's Name: Dmitry Didenko	
Time Reported: 12:00 am		

Type of moisture intrusion (clear, grey, black water):

Check Only One

		Inspector's Initials	Comments/Follow-up	
Clear		D.D.		
Grey	•	D.D.		
Black		D.D.		

Inspection Item:

Staining/discoloration observed on building materials:

Ceiling

Windows

Yes	No	Inspector's Initials	Comments/Follow-up	
	✓	D.D.		
1		D.D.		

Staining/discoloration observed near utilities:

Yes No Inspector's Initials Comments/Follow-up	Yes	s No	Inspector's Initials	Comments/Follow-up
--	-----	------	----------------------	--------------------

Building material impacted by moisture intrusion:

Location - which room / room(s) etc. Square Footages Wood moisture meter results

Concrete moisture meter results

fdvo		
IOVS		
juio		