Appendix B - Internal Moisture Intrusion Checklist

Clear

Grey Black

Perform as soon as possible after moisture intrusion problems are reported.

1 citorini do soon do possibile diferi moistare intrasion problems dre reported.			
Prope	rty Name: BEACON COVE	Unit# 8	
Date Reported: 10/12/22		Inspector's Name: Dmitry Didenko	
Time	Reported: 3:46 pm		

Type of moisture intrusion (clear, grey, black water):

Check Only One

	Inspector's Initials	Comments/Follow-up
	D.D.	
•	D.D.	
	D.D.	

Inspection Item:

Staining/discoloration observed on building materials:

Ceiling
Walls
Windows
Floor/tack strips

Yes	No	Inspector's Initials	Comments/Follow-up	
	✓	D.D.	zxc z	
✓		D.D.	zc	
	✓	D.D.	zc	
/		D.D.	c zcx	

Staining/discoloration observed near utilities:

Toilets
Sinks
Potable water lines
Drain lines
HVAC condensate pans/lines

Yes	No	Inspector's Initials	Comments/Follow-up
✓		D.D.	z zx
	1	D.D.	zx z
	✓	D.D.	zcx
1		D.D.	zx
	1	D.D.	zx

Building material impacted by moisture intrusion:

Location - which room / room(s) etc. Square Footages Wood moisture meter results Concrete moisture meter results

Hallways	AC Cabinet	Guest Bedroom
yukn6u	ryun	752
nuk	rynuj72	72
nyu	752	72

\$HcaHVACInspections->locations \$HcaHVACInspections->locations\$HcaHVACInspections->locations \$HcaHVACInspections->locations