Appendix B - Internal Moisture Intrusion Checklist

Perform as soon as possible after moisture intrusion problems are reported.

Perform as soon as possible after moisture	e intrusion problems are reporte	ս.
Property Name: SHADOWRIDGE HEIGHTS		Unit# 138
Date Reported: 10/14/21		Inspector's Name: Mark Gordillo
Time Reported: 12:00 am		

Clear

Grey Black

Type of moisture intrusion (clear, grey, black water):

Check Only One

	Inspector's Initials	Comments/Follow-up
	M.G.	
	M.G.	
1	M.G.	

Inspection Item:

 ${\bf Staining/discoloration\ observed\ on\ building\ materials:}$

Yes No Inspector's Initials	Comments/Follow-up
-----------------------------	--------------------

 $Staining/discoloration\ observed\ near\ utilities:$

Yes	No	Inspector's Initials	Comments/Follow-up

Building material impacted by moisture intrusion:

Location - which room / room(s) etc. Square Footages Wood moisture meter results Concrete moisture meter results

G/BATHROOM	G/BEDROOM

Remove and replaced effected drywall per Larry's scope of work on report