Appendix B - Internal Moisture Intrusion Checklist

Perform as soon as possible after moisture intrusion problems are reported.

1 ofform as soon as possible after moistare mit asion problems are reported.		
Property Name: BOULEVARD	Unit# 125	
Date Reported: 10/28/21	Inspector's Name: Mark Gordillo	
Time Reported: 12:00 am		

Type	of moisture	intrusion	(clear.	arev.	black	water):
- ypc	or moisture	III u u si u i	(CICUI,	grey,	Diucis	water).

Check Only One Grey
Black

Inspector's Initials		Comments/Follow-up
	M.G.	
	M.G.	
	M.G.	

Inspection Item:

 $Staining/discoloration\ observed\ on\ building\ materials:$

Yes No Inspector's Initials	Comments/Follow-up
-----------------------------	--------------------

 $Staining/discoloration\ observed\ near\ utilities:$

Yes	No	Inspector's Initials	Comments/Follow-up
-----	----	----------------------	--------------------

Building material impacted by moisture intrusion:

Location - which room / room(s) etc.
Square Footages
Wood moisture meter results
Concrete moisture meter results

M/BEDROOM	G/BEDROOM