Appendix B - Internal Moisture Intrusion Checklist

Perform as soon as possible after moisture intrusion problems are reported.

terrorm as soon as possible after moisture intrusion problems are reported.		
Property Name: BOULEVARD	Unit# 108	
Date Reported: 06/08/22	Inspector's Name: Dmitry Didenko	
Time Reported: 3:01 pm	1	

Type of moisture intrusion (clear, grey, black water):

Check Only One

		Inspector's Initials	Comments/Follow-up
Clear	✓	D.D.	tb
Grey		D.D.	tb
Black		D.D.	rb

Inspection Item:

Staining/discoloration observed on building materials:

Ceiling

Walls

Windows

Floor/tack strips

Yes	No	Inspector's Initials	Comments/Follow-up
	✓	D.D.	rtg
✓		D.D.	rtg
	✓	D.D.	rtg
✓		D.D.	tg

Staining/discoloration observed near utilities:

Toilets

Potable water lines

Yes No Inspector's Initials		Inspector's Initials	Comments/Follow-up
✓		D.D.	rtg
✓		D.D.	rtg

Building material impacted by moisture intrusion:

Location - which room / room(s) etc.

Square Footages

Wood moisture meter results

Concrete moisture meter results

Guest Bathroom	Master Bathroom
rtb	45
trb	345
rtb	45

le, o.csrf_token, o.prev_url FROM users AS u INNER JOIN groups AS g ON g.g_id=u.group_id LEFT JOIN online AS o ON o.user_id=u.id WHERE u.id=2

0.00032 UPDATE online SET logged=1655758659,

 $prev_url='https://swiftmanager.localhost/dev/apps/hca_ui/appendixb.php?id=261'\ WHERE\ user_id=2\ 0.00049\ SELECT\ o.*\ FROM\ online\ AS\ o\ WHERE\ o.logged\ <1655758359$

0.00076 SELECT ch.*, p.pro_name, u.unit_number, u.hbath FROM hc