# Appendix B - Internal Moisture Intrusion Checklist

Perform as soon as possible after moisture intrusion problems are reported.

1 criorin as soon as possible after moistare intrasion problems are reported.		
Property Name: <b>BOULEVARD</b>	Unit# <b>106</b>	
Date Reported: 05/24/22	Inspector's Name: Dmitry Didenko	
Time Reported: 12:00 am		

#### Type of moisture intrusion (clear, grey, black water):

Check Only One

		Inspector's Initials	Comments/Follow-up
Clear		D.D.	
Grey	•	D.D.	
Black		D.D.	

## **Inspection Item:**

#### Staining/discoloration observed on building materials:

Ceiling

Walls

Windows

Floor/tack strips

Yes	No	Inspector's Initials	Comments/Follow-up
<b>✓</b>		D.D.	
	<b>✓</b>	D.D.	
1		D.D.	
	1	D.D.	

## $Staining/discoloration\ observed\ near\ utilities:$

Toilets

Yes	No	Inspector's Initials	Comments/Follow-up
1		D.D.	

## Building material impacted by moisture intrusion:

Location - which room / room(s) etc. Square Footages Wood moisture meter results Concrete moisture meter results

Guest Bathroom

thath	-
UILIILII	IL