## **Appendix B - Internal Moisture Intrusion Checklist**

Perform as soon as possible after moisture intrusion problems are reported. Property Name: **DORCHESTER** Unit# **10E** Date Reported: 09/28/20 Inspector's Name: Mark Gordillo Time Reported: 12:00 am Type of moisture intrusion (clear, grey, black water): Inspector's Initials Comments/Follow-up Clear M.G. Check Only One Grey M.G. M.G. Black **Inspection Item:** Staining/discoloration observed on building materials: Inspector's Initials Yes No Comments/Follow-up Staining/discoloration observed near utilities: Yes No Inspector's Initials Comments/Follow-up Building material impacted by moisture intrusion: Location - which room / room(s) etc. L/ROOM Square Footages Wood moisture meter results

The paint has to be scraped off and paint. The left corner window upper side , drywall has to be repaired like 2x5. Might be the drain sistem has to be inspected becouse of the drainage not corectly seald next to  $21\ E$  balcony.

Concrete moisture meter results