Appendix B - Internal Moisture Intrusion Checklist

Perform as soon as possible after moisture intrusion problems are reported.

reflorm as soon as possible after moisture intrusion problems are reported.			
Property Name: BONITA HILLS	Unit# 1408D		
Date Reported:	Inspector's Name: Dmitry Didenko		
Time Reported:			

Type of moisture intrusion (clear, grey, black water):

Check Only One

		Inspector's Initials	Comments/Follow-up
Clear		D.D.	
Grey		D.D.	
Black	1	D.D.	

Inspection Item:

 $Staining/discoloration\ observed\ on\ building\ materials:$

Ceiling

Walls

Yes	No	Inspector's Initials	Comments/Follow-up
✓		D.D.	
	✓	D.D.	

Staining/discoloration observed near utilities:

Yes No

Inspector's Initials	Comments/Follow-up

Building material impacted by moisture intrusion:

Location - which room / room(s) etc.

Square Footages

Wood moisture meter results

Concrete moisture meter results

Guest Bathroom
ASc
sc
sc

ascas