Appendix B - Internal Moisture Intrusion Checklist

Perform as soon as possible after moisture intrusion problems are reported.

refrorm as soon as possible after moisture intrusion problems are reported.		
Property Name: ARBORS	Unit# A01	
Date Reported: 05/23/22	Inspector's Name: Dmitry Didenko	
Time Reported: 12:00 am		

Type of moisture intrusion (clear, grey, black water):

Check Only One

		Inspector's Initials	Comments/Follow-up
Clear		D.D.	
Grey	1	D.D.	
Black		D.D.	

Inspection Item:

Staining/discoloration observed on building materials:

Attics

Ceiling

Yes	No	Inspector's Initials	Comments/Follow-up
1		D.D.	
	1	D.D.	

Staining/discoloration observed near utilities:

Sinks

Yes	No	Inspector's Initials	Comments/Follow-up
	1	D.D.	

Building material impacted by moisture intrusion:

Location - which room / room(s) etc.

Square Footages

Wood moisture meter results

Concrete moisture meter results

Kitchen	Guest Bathroom	Master Bathroom
1	yh	ft
2	rg	by
3	tvvr	yh

rgbbrgvr
