# Appendix B - Internal Moisture Intrusion Checklist

Perform as soon as possible after moisture intrusion problems are reported.

reflorm as soon as possible after moisture intrusion problems are reported.			
Property Name: ARBORS	Unit# <b>A06</b>		
Date Reported: 05/20/22	Inspector's Name: Dmitry Didenko		
Time Reported: <b>6:50 pm</b>			

#### Type of moisture intrusion (clear, grey, black water):

Check Only One

		Inspector's Initials	Comments/Follow-up	
Clear J.D.D.		D.D.	sf	
Grey		D.D.	fs	
Black		D.D.		

### **Inspection Item:**

#### Staining/discoloration observed on building materials:

Attics

Ceiling Walls

Windows

Yes	No	Inspector's Initials	Comments/Follow-up
1		D.D.	
	<b>✓</b>	D.D.	
1		D.D.	
	1	D.D.	

### $Staining/discoloration\ observed\ near\ utilities:$

Potable water lines

Yes	No	Inspector's Initials	Comments/Follow-up
	1	D.D.	

# $\label{eq:building material impacted by moisture intrusion:} \\$

3				
Location - which room / room(s) etc.	Kitchen	GBath	MBath	HBath
Square Footages	s sdv	sdsvd	с	sdvsd
Wood moisture meter results	z vsd	sdvsd	с	sdvsdv
Concrete moisture meter results	zc v	sdvs	dv	sdvsd

advadvadv		
sdvsdvsdv		
Ja v Ja v Ja v		