Roof Report

March 21, 2026

Prepared by:

Repair King

680 Transfer Rd

Saint Paul , MINNESOTA 55114

mholmes@myrepairking.com

(612) 354-7677

1122 Dayton Avenue, Saint Paul, MN 55104

Powered by PG Reports™

©2025 Pitch Gauge LLC

Repair King
mholmes@myrepairking.com
(612) 354-7677
1122 Dayton Avenue, Saint Paul, MN 55104

Pitch Breakdown

Section **1**

(0/12) 296.22 ft²
(1/12) 21.31 ft²
(2/12) 90.31 ft²
(6/12) 260.59 ft²
(12/12) 2,276.03 ft²



Repair King
mholmes@myrepairking.com
(612) 354-7677

1122 Dayton Avenue, Saint Paul, MN 55104

Area Breakdown

Section **1**

29.4 SQs



©2025 Pitch Gauge LLC

Repair King
mholmes@myrepairking.com
(612) 354-7677
1122 Dayton Avenue, Saint Paul, MN 55104

Length Breakdown

Section **1**



Ridges:	73ft 9in	Wall Flashing:	116ft 10in
Eaves:	211ft 3in	Step Flashing:	17ft 4in
Rakes:	148ft 3in	Gutters:	0ft 0in
Valleys:	177ft 4in		
Hips:	129ft 3in	Others:	91ft 9in

©2025 Pitch Gauge LLC

Repair King
mholmes@myrepairking.com
(612) 354-7677

1122 Dayton Avenue, Saint Paul, MN 55104

Totals

Section **1**

Ridges:	73ft 9in
Eaves:	211ft 3in
Rakes:	148ft 3in
Valleys:	177ft 4in
Hips:	129ft 3in
Wall Flashing:	116ft 10in
Step Flashing:	17ft 4in
Gutters:	0ft 0in
Others:	91ft 9in
Tear Off:	29.44 SQs (2,944.47 ft²)

Waste Factor	5%	10%	12%	15%	18%	20%	22%	25%
Total Squares	30.92	32.39	32.98	33.86	34.74	35.33	35.92	36.81
Total Area ft²	3,092	3,239	3,298	3,386	3,474	3,533	3,592	3,681

We rely on 3rd party data including pictures, imagery, and software to obtain measurements that are as close as possible to the actual structure. Reports are usually within 96% or higher of the actual structures. You should always confirm quantities prior to ordering and ensure you are following local building code requirements.

Repair King
mholmes@myrepairking.com
(612) 354-7677
1122 Dayton Avenue, Saint Paul, MN 55104

Pitch Breakdown

Section **2**

(0/12) 92.68 ft²
(5/12) 528.29 ft²



©2025 Pitch Gauge LLC

Repair King
mholmes@myrepairking.com
(612) 354-7677
1122 Dayton Avenue, Saint Paul, MN 55104

Area Breakdown

Section **2**

6.2 SQs



©2025 Pitch Gauge LLC

Repair King
mholmes@myrepairking.com
(612) 354-7677

1122 Dayton Avenue, Saint Paul, MN 55104

Length Breakdown

Section **2**



Ridges:	23ft 9in	Wall Flashing:	5ft 9in
Eaves:	50ft 3in	Step Flashing:	1ft 0in
Rakes:	72ft 5in	Gutters:	0ft 0in
Valleys:	0ft 0in		
Hips:	0ft 0in		

©2025 Pitch Gauge LLC

Repair King
mholmes@myrepairking.com
(612) 354-7677

1122 Dayton Avenue, Saint Paul, MN 55104

Totals

Section **2**

Ridges:	23ft 9in
Eaves:	50ft 3in
Rakes:	72ft 5in
Valleys:	0ft 0in
Hips:	0ft 0in
Wall Flashing:	5ft 9in
Step Flashing:	1ft 0in
Gutters:	0ft 0in

Tear Off: 6.21 SQs (620.97 ft²)

Waste Factor	5%	10%	12%	15%	18%	20%	22%	25%
Total Squares	6.52	6.83	6.95	7.14	7.33	7.45	7.58	7.76
Total Area ft²	652	683	695	714	733	745	758	776

We rely on 3rd party data including pictures, imagery, and software to obtain measurements that are as close as possible to the actual structure. Reports are usually within 96% or higher of the actual structures. You should always confirm quantities prior to ordering and ensure you are following local building code requirements.

Repair King
mholmes@myrepairking.com
(612) 354-7677

1122 Dayton Avenue, Saint Paul, MN 55104

Totals

Section **All**

Ridges:	97ft 6in
Eaves:	261ft 6in
Rakes:	220ft 8in
Valleys:	177ft 4in
Hips:	129ft 3in
Wall Flashing:	122ft 7in
Step Flashing:	18ft 4in
Gutters:	0ft 0in
Others:	91ft 9in
Tear Off:	35.65 SQs (3,565.44 ft²)

Waste Factor	5%	10%	12%	15%	18%	20%	22%	25%
Total Squares	37.44	39.22	39.93	41.00	42.07	42.79	43.50	44.57
Total Area ft²	3,744	3,922	3,993	4,100	4,207	4,279	4,350	4,457

We rely on 3rd party data including pictures, imagery, and software to obtain measurements that are as close as possible to the actual structure. Reports are usually within 96% or higher of the actual structures. You should always confirm quantities prior to ordering and ensure you are following local building code requirements.

©2025 Pitch Gauge LLC