Roof Report

March 21, 2026

Prepared by:

Repair King

680 Transfer Rd

Saint Paul , MINNESOTA 55114

mholmes@myrepairking.com

(612) 354-7677

1773 Summit Avenue, Saint Paul, MN 55105

Powered by PG Reports™

©2025 Pitch Gauge LLC

Estimator Info

Data Input By:	Repair King 680 Transfer Rd Saint Paul , MINNESOTA 55114
Project Manager:	Mike
Email:	mholmes@myrepairking.com
Mobile:	

Client Info

Site Address:	1773 Summit Avenue Saint Paul, MN 55105

Repair King
mholmes@myrepairking.com
(612) 354-7677

1773 Summit Avenue, Saint Paul, MN 55105

Pitch Breakdown

Section **1**

(0/12) 545.73 ft²
(3/12) 17.11 ft²
(5/12) 28.42 ft²
(7/12) 2,469.99 ft²



©2025 Pitch Gauge LLC

Repair King
mholmes@myrepairking.com
(612) 354-7677
1773 Summit Avenue, Saint Paul, MN 55105

Area Breakdown

Section **1**

30.6 SQs



Repair King
mholmes@myrepairking.com
(612) 354-7677
1773 Summit Avenue, Saint Paul, MN 55105

Length Breakdown

Section **1**



Ridges:	17ft 10in	Wall Flashing:	59ft 3in
Eaves:	351ft 6in	Step Flashing:	58ft 3in
Rakes:	59ft 10in	Gutters:	0ft 0in
Valleys:	32ft 3in		
Hips:	192ft 11in		

©2025 Pitch Gauge LLC

Repair King
mholmes@myrepairking.com
(612) 354-7677

1773 Summit Avenue, Saint Paul, MN 55105

Totals

Section **1**

Ridges:	17ft 10in
Eaves:	351ft 6in
Rakes:	59ft 10in
Valleys:	32ft 3in
Hips:	192ft 11in
Wall Flashing:	59ft 3in
Step Flashing:	58ft 3in
Gutters:	0ft 0in

Tear Off: 30.61 SQs (3,061.26 ft²)

Waste Factor	5%	10%	12%	15%	18%	20%	22%	25%
Total Squares	32.14	33.67	34.29	35.20	36.12	36.74	37.35	38.27
Total Area ft²	3,214	3,367	3,429	3,520	3,612	3,674	3,735	3,827

We rely on 3rd party data including pictures, imagery, and software to obtain measurements that are as close as possible to the actual structure. Reports are usually within 96% or higher of the actual structures. You should always confirm quantities prior to ordering and ensure you are following local building code requirements.

Repair King
mholmes@myrepairking.com
(612) 354-7677

1773 Summit Avenue, Saint Paul, MN 55105

Pitch Breakdown

Section **2**

(5/12) 1,034.41 ft²



©2025 Pitch Gauge LLC

Repair King
mholmes@myrepairking.com
(612) 354-7677

1773 Summit Avenue, Saint Paul, MN 55105

Area Breakdown

Section **2**

10.3 SQs



©2025 Pitch Gauge LLC

Repair King
mholmes@myrepairking.com
(612) 354-7677
1773 Summit Avenue, Saint Paul, MN 55105

Length Breakdown

Section **2**



Ridges:	5ft 0in	Wall Flashing:	0ft 0in
Eaves:	124ft 0in	Step Flashing:	0ft 0in
Rakes:	0ft 0in	Gutters:	0ft 0in
Valleys:	0ft 0in		
Hips:	84ft 0in		

©2025 Pitch Gauge LLC

Repair King
mholmes@myrepairking.com
(612) 354-7677

1773 Summit Avenue, Saint Paul, MN 55105

Totals

Section **2**

Ridges:	5ft 0in
Eaves:	124ft 0in
Rakes:	0ft 0in
Valleys:	0ft 0in
Hips:	84ft 0in
Wall Flashing:	0ft 0in
Step Flashing:	0ft 0in
Gutters:	0ft 0in

Tear Off: 10.34 SQs (1,034.41 ft²)

Waste Factor	5%	10%	12%	15%	18%	20%	22%	25%
Total Squares	10.86	11.38	11.59	11.90	12.21	12.41	12.62	12.93
Total Area ft²	1,086	1,138	1,159	1,190	1,221	1,241	1,262	1,293

We rely on 3rd party data including pictures, imagery, and software to obtain measurements that are as close as possible to the actual structure. Reports are usually within 96% or higher of the actual structures. You should always confirm quantities prior to ordering and ensure you are following local building code requirements.

Repair King
mholmes@myrepairking.com
(612) 354-7677

1773 Summit Avenue, Saint Paul, MN 55105

Totals

Section **All**

Ridges:	22ft 10in
Eaves:	475ft 6in
Rakes:	59ft 10in
Valleys:	32ft 3in
Hips:	276ft 11in
Wall Flashing:	59ft 3in
Step Flashing:	58ft 3in
Gutters:	0ft 0in

Tear Off: 40.96 SQs (4,095.67 ft²)

Waste Factor	5%	10%	12%	15%	18%	20%	22%	25%
Total Squares	43.00	45.05	45.87	47.10	48.33	49.15	49.97	51.20
Total Area ft²	4,300	4,505	4,587	4,710	4,833	4,915	4,997	5,120

We rely on 3rd party data including pictures, imagery, and software to obtain measurements that are as close as possible to the actual structure. Reports are usually within 96% or higher of the actual structures. You should always confirm quantities prior to ordering and ensure you are following local building code requirements.