

CO₂ Concentration ○ 600 ppm 1000 ppm 2500 ppm Calibration 1. Refresh the room very well 2. Press and hold the top button until led light will be blue