

Safe Materials

The materials that the laser can cut, are materials like wood, paper, cork, and some kinds of plastics. Etching can be done on almost anything, wood, cardboard, aluminum, stainless steel, plastic, marble, stone, tile, and glass.

Cutting

Material	Max thickness	Notes	WARNINGS!	
Many woods	1/4"	Avoid oily/resinous woods	Be very careful about cutting oily woods, or very resinous woods as they also may catch fire.	
wood/Composite woods	1/4"	These contain glue, and may not laser cut as well as solid wood.		
MDF/Engineered woods	1/4"	These are okay to use but may experience a higher amount of charring when cut.		
Paper, card stock	thin	Cuts very well on the laser cutter, and also very quickly.		
Cardboard, carton	thicker	Cuts well but may catch fire.	Watch for fire.	
Cork	1/4"	Cuts nicely, but the quality of the cut depends on the thickness and quality of the cork. Engineered cork has a lot of glue in it, and may not cut as well.	Avoid thicker cork.	
Acrylic/Lucite /Plexiglas/PMMA	1/2"	Cuts extremely well leaving a beautifully polished edge.		
Thin Polycarbonate Sheeting (<1mm)	<1mm	Very thin polycarbonate can be cut, but tends to discolor badly. Extremely thin sheets (0.5mm and less) may cut with yellowed/discolored edges. Polycarbonate absorbs IR strongly, and is a poor material to use in the laser cutter. Watch for smoking/burning		
Delrin (POM)	thin	Delrin comes in a number of shore strengths (hardness) and the harder Delrin tends to work better. Great for gears!		
Kapton tape (Polyimide)	1/16"	Works well, in thin sheets and strips like tape.		
Mylar	1/16"	Works well if it's thin. Thick mylar has a tendency to warp, bubble, and curl	Gold coated mylar will not work.	
Solid Styrene	1/16"	Smokes a lot when cut, but can be cut.	Keep it thin.	
Depron foam	1/4"	Used a lot for hobby, RC aircraft, architectural models, and toys. 1/4" cuts nicely with a smooth edge. Must be constantly models.		
Gator foam		Foam core gets burned and eaten away compared to the top and bottom hard paper shell.	Not a fantastic thing to cut, but it can be cut if watched.	
Cloth/felt/hemp/cotton		They all cut well. Our "advanced" laser training class teaches lace-making. Not plastic coated or impregr cloth!		
Leather/Suede	1/8"	Leather is very hard to cut, but can be if it's thinner than a belt (call it 1/8"). Our "Advanced" laser training class covers this. Real leather only! Not ' other imitations!		
Magnetic Sheet		Cuts beautifully		
NON-CHLORINE- containing rubber		Fine for cutting. Beware chlorine-containing rubber		
Teflon (PTFE)	thin	Cuts OK in thin sheets		
Carbon fiber mats/weave that has not had epoxy applied		Can be cut, very slowly.	You must not cut carbon fiber that has been coated!!	
plast ('corrugated plastic')	1/4"	Difficult because of the vertical strips. Three passes at 80% power, 7% speed, and it will be slightly connected still at the bottom from the vertical strips.		



Etching

All the above "cut-able" materials can be etched, in some cases very deeply. In addition, you can etch:

Material	Notes	WARNINGS!
Glass	Green seems to work best…looks sandblasted.	Only FLAT GLASS can be engraved. No round or cylindrical items.
Ceramic tile		
Anodized aluminum	Vaporizes the iodization way.	
Painted/coated metals	Vaporizes the paint away.	
Stone, Marble, Granite, Soapstone, Slate Onyx.	Gets a white "textured" look when etched.	100% power, 50% speed or less works well for etching.