User Manual

1. Command Line checking for parameters

```
Steps:
```

```
a) $$export EPICS_CA_ADDR_LIST=/*ip of server*/
```

b) \$\$export EPICS_CA_AUTO_ADDR_LIST=NO

c) \$\$caget arg1

arg1=PV name

//displays current value of the process variable

d) \$\$camonitor arg1

arg1=PV name

//monitors and displays the PV Value at regular intervals

e) \$\$caput arg1 arg2

arg1=PV name

arg2=PV value to be set

2. MEDM

Steps:

a) \$\$export EPICS_CA_ADDR_LIST=/*ip of server*/

b) \$\$export EPICS_CA_AUTO_ADDR_LIST=NO

c) \$\$medm

Or

\$\$cd /opt/epics/extensions/bin/arg1

arg1=architecture of the client machine

\$\$./medm arg1

arg1=Path to the .adl file

3. caQtDM

Steps:

```
a) $$export EPICS_CA_ADDR_LIST=/*ip of server*/
```

- b) \$\$export EPICS_CA_AUTO_ADDR_LIST=NO
- c) \$\$caqtdm

Or

\$\$cd /opt/epics/extensions/bin/arg1

arg1=architecture of client machine

\$\$./caQtDM arg1

arg1=path to .ui file

4. Strip Tool

Steps:

- a) \$\$export EPICS_CA_ADDR_LIST=/*ip of server*/
- b) \$\$export EPICS_CA_AUTO_ADDR_LIST=NO
- c) \$\$strip_tool

or

\$\$cd /opt/epics/extensions/bin/arg1

arg1=architecture of client machine

\$\$./StripTool

- e) Click on load option in file menu
- f) Select .stp file
- g) Click on graph option in window menu
- h) Click on the PV name displayed on the right side to view it's axis markings

5. ca Save Restore

Steps:

- a) \$\$export EPICS_CA_ADDR_LIST=/*ip of server*/
- b) \$\$export EPICS_CA_AUTO_ADDR_LIST=NO
- c) \$\$cd /opt/epics/extensions/bin/arg1 arg1=architecture of client machine
- d) \$\$./casave –asciiin arg1 –asciiout arg2 –log arg arg1=path to the request ascii file arg2=path to the snap file arg3=path to the log file
- e) \$\$./carestore –asciiin arg1 –log arg2 arg1=path to snap ascii file arg2=path to log file

6. Alarm Handler

Steps:

- a) \$\$export EPICS_CA_ADDR_LIST=/*ip of server*/
- b) \$\$export EPICS_CA_AUTO_ADDR_LIST=NO
- c) \$\$alh

Or

\$\$ cd /lib64/epics/extensions/bin/arg1 arg1=architecture of client machine

\$\$./alh arg2 arg2=path to the .alhConfig file

7. CA Watcher

Steps:

- a) \$\$export EPICS_CA_ADDR_LIST=/*ip of server*/
- b) \$\$export EPICS_CA_AUTO_ADDR_LIST=NO
- c) \$\$java -jar arg1

arg1=path to the cawatcher jar file

d) Enter Process variables to monitor and save