

CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-2016865-1
Report Reference E504391-20210212
Date 16-Aug-2022

Issued to: Wenzhou Fahint Electric Co Ltd
Xinguang Ave 130#, Xinguang Industrial Zone
Liushi Town, Yueqing
(In Gelun Electric Co.,Ltd) Wenzhou, Zhejiang 325600
China

**This is to certify that
representative samples of** KCXS - Ground-fault Circuit Interrupters
See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 943, 5th Ed., Issue Date: 2016-05-17, Revision Date:
2018-02-23

Additional Information: See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>




CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-2016865-1
Report Reference E504391-20210212
Date 16-Aug-2022

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
GF15	Receptacle Auto-Monitoring Ground Fault Circuit Interrupters
GF20	Receptacle Auto-Monitoring Ground Fault Circuit Interrupters
GT15	Receptacle Auto-Monitoring Ground Fault Circuit Interrupters Tamper Resistant
GT20	Receptacle Auto-Monitoring Ground Fault Circuit Interrupters Tamper Resistant
GTN15	Receptacle Auto-Monitoring Ground Fault Circuit Interrupters Tamper Resistant and No Feed Thru
GTN20	Receptacle Auto-Monitoring Ground Fault Circuit Interrupters Tamper Resistant and No Feed Thru
GW15	Receptacle Auto-Monitoring Ground Fault Circuit Interrupters Tamper Resistant and Weather Resistant
GW20	Receptacle Auto-Monitoring Ground Fault Circuit Interrupters Tamper Resistant and Weather Resistant



Bruce Mahrenholz, Director North American Certification Program

UL LLC



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-2013435-1
Report Reference E504391-20210212
Date 16-Aug-2022

Issued to: Wenzhou Fahint Electric Co Ltd
Xinguang Ave 130#, Xinguang Industrial Zone
Liushi Town, Yueqing
(In Gelun Electric Co., Ltd) Wenzhou, Zhejiang 325600
China

This is to certify that representative samples of KCXS7 - Ground-fault Circuit Interrupters Certified for Canada
See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.


Standard(s) for Safety: CSA C22.2 NO. 144.1-16, 2nd Ed., Issue Date: 2016-05-17, Revision Date: 2018-02-01

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-2013435-1
Report Reference E504391-20210212
Date 16-Aug-2022

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
GF15	Receptacle Auto-Monitoring Ground Fault Circuit Interrupters
GF20	Receptacle Auto-Monitoring Ground Fault Circuit Interrupters
GT15	Receptacle Auto-Monitoring Ground Fault Circuit Interrupters Tamper Resistant
GT20	Receptacle Auto-Monitoring Ground Fault Circuit Interrupters Tamper Resistant
GTN15	Receptacle Auto-Monitoring Ground Fault Circuit Interrupters Tamper Resistant and No Feed Thru
GTN20	Receptacle Auto-Monitoring Ground Fault Circuit Interrupters Tamper Resistant and No Feed Thru
GW15	Receptacle Auto-Monitoring Ground Fault Circuit Interrupters Tamper Resistant and Weather Resistant
GW20	Receptacle Auto-Monitoring Ground Fault Circuit Interrupters Tamper Resistant and Weather Resistant



Bruce Mahrenholz, Director North American Certification Program

UL LLC



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>