gEDA assignment

CREATE A SCHEMATIC FILE, PCB FILE, NETLIST AND A OUTPUT GERBER FILE FOR THE ATTACHED SCHEMATIC, FOLLOWING THE GUILDLINES BELOW.

- 1. Schematic should look as close as possible to the attached image, appropriate fields of each component should be filled in *gschem* for the same.
- 2. Nets in *gschem* should be labelled and the same should reflect in the netlist file.
- 3. The footprints are as follows:
 - 1. All resistors are SMD [0603].
 - 2. Caps are appropriate sized through holes.
 - 3. Transistors are through hole.
 - 4. Leds are SMD [0806]
 - 5. Attiny is a DIP8
 - 6. PINHD is a 6 pin through hole header.
 - 7. Crystal is SMD, any size
 - 8. Switch is Push button through hole
 - 9. The battery can be taken as a 2 pin header.
- 4. All SMD components should lie on the component side of the PCB, i.e. we have a two sided PCB

Enjo	Эy,

Akshat

