ZF6HP19/26/32*



Oversized Converter Release Regulator Valve Kit

Helps cure:

- Excessive TCC slip, RPM & related codes
- Harsh lockup apply & release

Note: Requires tool kit F-95740-TL5 & the VB-FIX reaming fixture.

(2) 95740-11K



Helps cure:

- Low converter pressure
- Lube failure

Note: Requires tool kit F-95740-TL11 & the VB-FIX reaming fixture.

95740-13K



Oversized Bypass Clutch Control Valve Kit

Helps cure:

- Converter overheat
- Low TCC release pressure

Note: Requires tool kit F-95740-TL13 & the VB-FIX reaming fixture.

95740-03

Pressure Regulator Sleeve

Helps cure:

- Harsh or erratic line pressure
- Broken parts



Oversized Pressure Regulator Valve Kit



- Delayed or no reverse
- Poor shift quality

Note: Requires tool kit F-95740-TL & the VB-FIX reaming fixture.



©2011 Sonnax Industries, Inc.





Oversized Solenoid Pressure Regulator Valve Kit

Helps cure:

- Gear ratio or solenoid codes
- Wrong gear starts

Note: Requires tool kit F-95740-TL17 & the VB-FIX reaming fixture.

95740-08K

Oversized Clutch D1 or E Control Valve Kit



Helps cure:

- Flare upshifts or downshift bind-ups
- Excessive clutch overlap & clutch distress

Note: Requires tool kit F-95740-TL8 & the VB-FIX reaming fixture.

(8) 95740-09K



Oversized Clutch A Control Valve Kit

Helps cure:

- Flare upshifts or downshift bind-ups
- Excessive clutch overlap & clutch distress

Note: Requires tool kit F-95740-TL8 & the VB-FIX reaming fixture.

(9) 95740-21K

Clutch A Control Boost Valve & Sleeve Kit

- Delayed/Harsh forward engagement
- Flare/Neutral on 5-4 downshift

(10) 95740-15K

Valve Body Accumulator Piston & Spring Kit

6 Sets

Helps cure:

- Firm up/downshift and/or engagement
- Erratic EDS solenoid control

(11) 95740-19K

6 large & 6 small plugs

(12) 95740-25K

4 plugs (Internal)

O-Ringed End Plug Kits

Helps cure:

• Soft/Inconsistent shift feel