55211-04K

TCC Regulator Valve & Sleeve Kit



Helps cure:

- TCC slip/ratio codes
- Transmission/Converter overheat

Note: Requires tool kit F-55211-TL4 & the VB-FIX reaming fixture.

(2) 55211-21



TCC Control Valve Helps cure:

For single valve pumps

- Incorrect TCC apply & release
- No lockup/falling out of lockup hot

Note: Requires tool kit F-55211-TL22, & the VB-FIX reaming fixture

(3) 55211-22K



TCC Control & Enable For dual valve pumps

Valve Kit Helps cure:

- Incorrect TCC apply & release
- No lockup/falling out of lockup hot

Note: Requires tool kit F-55211-TL22, & the VB-FIX reaming fixture.

55211-08K



Fluid Pump

Assembly

4

Pressure Regulator Valve & Sleeve Kit

Helps cure:

2

- Low line pressure
- Worn PR valve bore

Note: Requires tool kit 55211-TL8.

1 Automatic Drive • P.O. Box 440 • Bellows Falls, VT 05101-0440 USA (800) 843-2600 • (802) 463-9722 • F: (802) 463-4059 • www.sonnax.com



©2011 Sonnax Industries, Inc.



Valve spool diameters

Boost Valve, Sleeve & Spacer Kit

- Insufficient line rise/high reverse pressure
- Flare upshifts
- (6) 55209-04K

Valve spool diameters .474" & .441"

Boost Valve & Sleeve Kit

Helps cure:

- Insufficient line rise/high reverse pressure
- Flare upshifts
- 7 55211-01K





- Reduced line pressure
- Gear ratio slip codes

Note: Requires tool kit F-55211-TL & the VB-FIX reaming fixture.

(8) 55211-17K





Helps cure:

- 3-2-1 Bump on coast downshifts
- Harsh/No engine braking in 1st, 2nd or 3rd

Note: Requires tool kit F-55211-TL17 & the VB-FIX reaming fixture.

(9) 55211-11K

Helps cure:






- Loss of reverse
- TCC overheat

Note: Requires tool kit F-55211-TL & the VB-FIX reaming fixture.

(10) 55211-14K



Valve Kit



Helps cure:

- 1-2 Bind-up, 3-4 Shift flare
- 4-5 Shift complaints, Clutch distress

Note: Requires tool kit F-55211-TL14 & the VB-FIX reaming fixture.



