
## PX4B ('90 HONDA ACCORD)



Notes: Very low flush at 45 degrees F, .3 gpm Park, Reverse, Drive. Flow sensitive to rpm and .4-.6 gpm during shift. Unit has been flushed on DCI HOT FLUSH and flowed well.