# CD4E, LA4A-EL

**PART NUMBER 73251-01K** 

# COMPLAINT

SECONDARY COMPLAIN

## Causi

The factory shims do not offer an adequate selection for proper endplay adjustment

## CORRECTION

This shim kit offers a more precise endplay adjustment for the gear train and final drive.

### Shim Kit for Setting Endplay

#### 73251-01K

2 Shims


.008" & .015" thick for #9 Bearing

2 Shims

.005" & .010" thick for #13 Bearing

### **Excessive endplay**

• Lube failures



#### **Sonnax Part Summary**

Sonnax now offers a shim kit **73251-01K** to adjust both the planet-to-drum endplay and the differential endplay. These shims offer a finer endplay adjustment than the OEM selective washers, resulting in a more precise endplay setting.

