4L60-E PWM & NON-PWM

PART NUMBER 77754-ISO

Isolator Valve Sleeve Kit

77754-ISO


1 Isolator Valve Sleeve1 Retaining Clip



Note: U.S. Patent No. 6,990,996 & 7,104,273



More technical information is available at www.sonnax.com. Type in this part number under "Part Finder."



Wet Air Test to check for isolator bore leakage

To test for a signal oil leak, place oil into the PWM/TCC feed (2nd clutch oil on non-PWM units, see photos below). Follow with low air pressure. There should be minimal/no leakage through the exhaust port.

