PART NUMBERS 36941-03-BST

COMPLAINT

Downshift or engine braking problems

• No cutback line rise • Fixed high line pressure

CAller

Narrow spool width on the 2nd spool diameter causes this diameter and bore to wear excessively, causing the valve to stick and hang up in the bore.

Correction

This replacement valve will eliminate the 2nd valve spool from sticking or hanging up in the valve bore.

Line Pressure Coasting Regulator Valve & Bore Sizing Tool


36941-03

1 Line Pressure Coasting Regulator Valve



36941-BST

1 Bore Sizing Tool



Sonnax Part Summary

An incorrect length-to-diameter ratio of the 2nd spool valve causes the valve to stick or hang up in the valve bore. This replacement line pressure coasting regulator valve **36941-03** will restore smooth valve actuation and properly regulate coastdown line pressure.

Features & Benefits

- Replacement valve has increased spool length with exhaust flats that will eliminate the 2nd valve spool from sticking or hanging up in the valve bore.
- Annular grooves have been provided on the long spool diameter to improve valve oil distribution, and reduce valve sideloading.
- Bore-sizing tool removes bore ridges created by sticking or hung up valve.

Note: For this replacement valve to work properly, the valve bore must be resized for smooth valve actuation. Use Sonnax valve bore-sizing tool **36941-BST** to refurbish the OEM valve bore.



\$100 in valve body replacement costs

