

FD-N-6 Bearing Update / OEM Changes / Ford 4R100 & 5R110W

The turbine hub bearing **FD-N-6** has been updated and has a new look. The race is now black and no longer has the blue stripes painted on the face. It now incorporates a snap-in configuration requiring more pressure to assemble the bearing to the turbine hub. This feature helps prevent the race from spinning on the turbine hub.



©2007 Sonnax Industries, Inc.

FD-N-6 Tech Advisory 8-7-07