

FD-HT-16HS

Ford CD4E Turbine Hub with Hardened Splines



- Induction Hardened Internal Splines
- Associated Parts:

 FD-O-7V Radial Lip Seal
 FD-O-8V Viton O-Ring
 FD-RV-1 Rivets (10 required)

This Ford Turbine Hub is item #13 on page 71 in our 1998 Torque Converter Parts Catalog!



Sonnax part number FD-HT-16HS provides rebuilders with a hardened spline option for replacing damaged CD4E turbine hubs.

©1998 Sonnax Industries, Inc. November '98