## **Application Cheat Sheet**

Raybestos POWERTRAIN	EC°	PWM	ON/OFF	Heavy Duty	High Performance	Temperature Resistance 1=Highest 5=Lowest	Torque Capacity 1=Highest 5=Lowest
(T) Tan Organic Paper			•			5	2
(K) High Energy Kevlar®		•				3	3
(HC) High Carbon Paper		•				2	4
(SW Carbon™) Carbon Fiber	•					1	5
(PT) Pow erTorque™				•	•	4	1



