
## MPZA ('96 Honda Accord V-6 2.7L 103,000 miles)



Notes: Park cooler flow was stable for 5 seconds at .8, then goes up for 5 seconds at 1.1, then down to .6. Reverse and neutral also go up for 5 seconds and then settle down.