

ORQUE CONVERTER COMPONENTS



FD-DA-19PB

Piston Plate

Application:

- Ford AX4S, AX4N (4F50N) single clutch converters
- Ford CD4E 3.0L Escape
- Mazda CD4E 3.0L Tribute

Details:

- Replaces the OEM piston that is prone to cracking
- Machined from a steel forging
- Increased wall thickness for greater stiffness (.200" Thick)
- Lock-up surface machined to specific requirements to ensure a great bond

Associated Parts:

- 466300PT PowerTorque® Friction Ring (9.50" O.D., 8.25" I.D., .066" Thick)
- FD-0-12 Seal Ring, full circle
- FD-0-16 Seal Ring, scarf cut



FD-DA-19PB

Piston Plate

Prepackaged Quantity: 1 Unit

The AX4S, AX4N (4F50N) single clutch converters have a piston that is prone to cracking due to manufacturing flaws. A cracked piston will not only lock up improperly but will shave material off the OEM friction ring. This loose friction material will contaminate the whole transmission. The Sonnax **FD-DA-19PB**, a fully machined forging, is a replacement piston plate that corrects this OEM problem. 466300PT PowerTorque® Friction Ring is recommended for use with FD-DA-19PB.

Please refer to our

TORQUE CONVERTER PART CATALOG VOLUME 6 & ONLINE CATALOG AT WWW.SONNAX.COM

FD-DA-19PB replaces:

Item Number 17 for AX4S, AX4N (4F50N) on page 84 and Item Number 16 for CD4E 9-1/4 3.0L Escape and Tribute on page 90.