
AXODE



Event: After 1-2 shift and between 35-55 mph. **Condition:** Misdiagnosed as engine surge.

Correction: Install Sonnax Boost Valve 96201-01K, Bypass Clutch Control Sleeve Kit **96206-01K**, and new valve body relief tees.