

GM 8" OPEL

MECHANCAL DIODE REFRESHER KIT

HIGH PERFORMANCE TORQUE CONVERTER PARTS

Part No.

GM-MD-RK


Refresher Kit

NOTE: This refresher kit can be used to rebuild Sonnax mechanical diodes GM-MD-3, GM-MD-3DP, GM-MD-3UA, CH-MD-1, FD-MD-2, FDGM-MD-1 and GMFD-MD-1.


INSTALLATION INSTRUCTIONS

1. Place the core on a suitable work area with the spring and strut cavities facing up.

NOTE: Proper positioning of the spring and strut are critical for correctly assembling the unit.



Orient the spring as shown in Figure
When installed correctly, the spring will look like the one shown in Figure
1.



- 5. The load-bearing edges of the strut are angled and should appear as shown in Figure 4 when installed.
- 6. Place the notch plate with the spiral ring groove (ring groove facing down) onto the core. You will begin to feel spring tension as the plate comes into contact with the struts. Continue pushing the plate down until the springs are fully compressed. Hold the two parts firmly together and turn the assembly over to expose the spiral ring groove. If the ring groove is not visible, the springs and struts are not installed correctly.
- 7. Continue holding the parts together and install the spiral snap ring.






Figure 2



Wide tab goes toward outside



©2008 Sonnax Industries, Inc.