
4R70W ('95-HIGH MILEAGE)



Condition: Aerated fluid (pump grabbing air), poor suction porting, gaskets, etc.

Correction: New pump, Sonnax Bypass Clutch Control Sleeve & Plunger Valve **76948-04K**, pressure regulator valve and converter regulator valve.

Notes: Initial start, then reverse engagement. Can occur at end of 1-2 shift.