## 4L80-E

Sonnax

onnax Sure Cure® Kits

Sonnax products into one box, offering rebuilders a convenient and cost-effective way to address common transmission problems. These kits simplify ordering, stocking and estimating job costs, and include easy-to-read, step-by-step instructions that cover the inspection and repair of the most critical areas of the unit, and even a reference list of rebuilding specifications.

ᇻ

Rebu



## This 4L80-E transmission reconditioning kit includes the following Sonnax parts and addresses these problems:

Sonnax Part:	The SureCure® for:
• Boost valve kit ( <b>34200-01K</b> )	High line pressure, broken hard parts
• Wide stator bushing (34016-W)	No lockup; codes 68, 1870
TCC and PR valve end plugs (34994-11, -13, -14 & 34200-05)	Low pressure caused by end plug leaks
• AFL valve kit ( <b>34200-16K</b> ) J.S. Pat. No. 6,634,377	Wrong gear starts, solenoid codes, band failure & no 4th gear
TCC regulator valve kit (34994-01K)	Converter shudder; codes 68, 1870
Shift valve spring kit (34994-02K)	2nd gear starts, 3-1 neutral, no 3rd or 4th
• Torlon <sup>®</sup> checkballs (10000-08)	Circuit leaks
• Spring pins (34997-07 & -09)	Convenient replacement pins for multiple locations
No-walk case bushing (34006-SP)	Case bushing "walks out," delayed forward engagement
Endplay washer (34301-078)	Excessive unit endplay
• Endplay shim ( <b>34500-Z</b> )	Forward clutch & sealing ring failures, excessive endplay
Required Tools:	
77754-TL	Tool kit for AFL valve

©2004 Sonnax° SC-4L80E (rb) 12/23/04