

# TORQUE CONVERTER PARTS FD-DA-17PBF CLUTCH CONVERSION PLATE WITH FRICTION RING BONDED

### **Application:**

• Ford 5R55N/S/W

#### **Details:**

- Replaces noisy OEM multi-plate clutch assembly
- Machined from a steel forging
- Increased wall thickness for greater stiffness (.200" thick)
- Includes 466570PT, bonded Raybestos®
   PowerTorque™ Friction Ring, 9" X 7.50" X .066"

#### **Associated Parts:**

- FD-DA-17PB, unbonded Clutch Conversion Plate
- FD-O-14, Seal Ring, full circle, OEM version
- FD-O-15, Seal Ring, scarf cut



#### Part No.

## **FD-DA-17PBF**

Clutch Conversion Plate/Friction Ring Bonded

# Sold in prepackaged quantities of 1 unit

Please refer to our

# TORQUE CONVERTER PARTS CATALOG VOLUME 6 & ONLINE CATALOG AT WWW.SONNAX.COM FD-DA-17PBF replaces:

Item Numbers 19, 20 and 21 for Ford 5R55N/S/W on page 68.

The 5R55N/S/W converter may have weak and/or broken spring clips and a worn mating piston, causing noise in this unit. Bending or replacing the spring clips is only a temporary fix. **FD-DA-17PBF** is a drop-in replacement piston plate that uses the existing damper, but converts the clutch from a two- to one-friction ring piston. This eliminates the noise problem found in the OEM units. This piston includes a bonded Raybestos PowerTorque<sup>TM</sup> friction ring.

Note: This piston may not be suitable for high performance or heavy-duty towing applications.

©2008 Sonnax Industries, Inc. FD-DA-17PBF 01-10-08