
## Sonnax is Geared-Up for



\*These Solutions may be used in Mitsubishi F4A41/42/51, R4/V4A51, R5/V5A51, F5A51, A5HF1 & A5GF1; 1996 - Up.

Multiple valve body styles and configurations exist. More information is available at www.sonnax.com



2. 41954-06K A: No Orifice 41954-07K B: With Orifice

**Pressure Control Valve** and Sleeve Kits

### Helps cure:

- Shift/flare or shuttle shifts
- Cycling RPM during shift
- Delayed engagements

3. 41954-01K FWD Units Only

### **Oversized Pressure Regulator Valve**

### Helps cure:

- Low/high line pressure
- Soft/harsh shifts
- Low converter pressure



Note: Requires tool kit F-41954-TL & the VB-FIX reaming fixture.

## 4. 41954-03K

**TCC Control Valve** and Sleeve Kit

### Helps cure:

- Converter apply/release issues
- Excess slip RPM
- Cycling TCC RPM



1. 41954-02K

Helps cure:

• Soft/harsh shifts

**Accumulator Piston** 

• Worn accumulator bores

• Delayed/Shuddering engagements

with Dual Seals



Automatic Drive . P.O. Box 440 . Bellows Falls, Vermont 05101-0440 USA 800-843-2600 • 802-463-9722 • F: 802-463-4059 • www.sonnax.com • info@sonnax.com ©2009 Sonnax Industries, Inc.

# Popular Mitsubishi Family\*

