Sonnax Delivers RE5R05A* Valve Body Solutions!

1. 63741-05K

TCC Control Sleeve Assembly

Helps cure:

- Lockup shudder
- TCC cycling
- Burnt converters

2. 63741-07K

Cooler Bypass Valve Kit

Helps cure:

- Fluid overheat
- Diminished lubrication







TC Regulator Kit

Helps cure:

- Converter related complaints & codes
- Damaged TCC linings
- Lube failures

Note: Requires tool kit F-63741-TL13 & the VB-FIX reaming fixture.



Late Style

5. 63741-12K

Early Style

Reverse Boost Valve Kits

Helps cure:

- Delay in reverse or slipping
- Burnt clutches

6. 63741-01K

Oversized Pressure Regulator Valve & Reverse Boost Assembly



- High line pressure
- Reduced converter & lube flow
- Delayed forward/harsh reverse

Note: Requires tool kit F-63741-TL & the VB-FIX reaming fixture.





FIXTURE








Accumulator Control Valve Repair Kit

Helps cure:

- Shift feel complaints
- Shift feel related codes
- Accumulator oil leakage

Note: Requires tool kits F-63741-TL13 & the VB-FIX reaming fixture.





- Erratic shifts
- Delayed or loss of forward and/or reverse

Note: Requires tool kit F-63741-TL13 & the VB-FIX reaming fixture.



Automatic Drive • P.O. Box 440 • Bellows Falls, Vermont 05101-0440 USA 800-843-2600 • 802-463-9722 • F: 802-463-4059 • www.sonnax.com • info@sonnax.com