



THROTTLE VALVE KIT

HIGH PERFORMANCE TRANSMISSION PARTS

FEATURES & BENEFITS:

- Corrects late 2-3 upshifts
- Corrects oversensitive
 3-2 downshifts
- Corrects throttle buzz
- Reduces soft shifts



1 Throttle Valve

1 Throttle Plunger


1 Balance Spring

3 Spring Shims

1 Alternative TV Spring

1 Sleeve

Note: The modified TV spring should never be installed alone. Always use at least one shim with spring.



PART SUMMARY

Vehicles with A904-A727, 42RH/RE and 47RH/RE transmissions may have problems with late 2-3 upshifts and oversensitive 3-2 downshifts. These complaints are often due to excessive wear between the throttle valve and throttle valve sleeve. Sonnax now offers the **22771-HKD** throttle valve kit. This kit works well in towing applications where oversensitive 3-2 downshifts are a problem.

©2004 Sonnax[®] 22771-HDK (info) 05-11-04