1 1 DU-L ('97 & UP) Part No. SC-4T60E-1



onnax Sure Cure® Kits combine "the best" Sonnax products into one box, offering rebuilders a convenient and cost-effective way to address common transmission problems. These kits simplify ordering, stocking and estimating job costs, and include easy-to-read, step-by-step instructions that cover the inspection and repair of the most critical areas of the unit, and even a reference list of rebuilding specifications.

4

7

Rebu



This 4T60-E ('97 & up) transmission reconditioning kit includes the following Sonnax parts and addresses these problems:

Sonnax Part:	The SureCure® for:
• TCC regulator valve assembly (84754-01K)	Code 1870, converter shudder
• TCC apply valve kit (84754-97K) Patent Pending	Code 1870, falling out of lockup hot
<ul> <li>Reverse boost valve assembly (84754-19K)</li> </ul>	Poor reverse boost
<ul> <li>Modulated line boost valve assembly (84754-17K)</li> </ul>	Soft shifts, poor line rise
Pump slide pivot pin (84881A)	Low or high line pressure
<ul> <li>Imidized plastic check balls (10000-08 &amp; 10000-09)</li> </ul>	Upgraded replacement for steel OEM check balls
• Differential side gear thrust washer (75890-30)	Hardened thrust washer allow service of differential
• Endplay shims (84733-10 & 20, 75410-10)	Drive line engagement clunk
Boost valve retainer clip (84754-27)	Replacement clip for broken or missing OEM clips
Recommended Tools:	
84754-TL5	TCC apply valve reamer and drill ligs

©2003 Sonnax° SC-4T60-1 (rb) 12/03/03