4T60-E ('93-'98

Part No. SC-4T60E



onnax Sure Cure® Kits combine "the best" Sonnax products into one box, offering rebuilders a convenient and cost-effective way to address common transmission problems. These kits simplify ordering, stocking and estimating job costs, and include easy-to-read, step-by-step instructions that cover the inspection and repair of the most critical areas of the unit, and even a reference list of rebuilding specifications.

7

Rebu



This 4T60-E ('93-'96) transmission reconditioning kit includes the following Sonnax parts and addresses these problems:

• TCC regulator valve assembly (84754-01K)	Code 1870/740, converter shudder
• TCC apply valve kit (84754-16K) Patent Pending	Code 1870/740, falling out of lockup hot
• Reverse boost valve assembly (84754-19K)	Poor reverse boost
• Modulated line boost valve assembly (84754-17K)	Soft shifts, poor line rise
• 1-2 roller clutch spring kit (K84956-SP)	Weak OEM springs, no movement and rattle in park
Pump slide pivot pin (84881)	Low or high line pressure
• Imidized plastic check balls (10000-08 & 10000-09)	Upgraded replacement for steel OEM checkballs
• Differential side gear thrust washer (75890-30)	Hardened thrust washer allow service of differential
• Endplay shims (84733-10 & 20, 75410-10)	Drive line engagement clunk
Boost valve retainer clip (84754-27)	Replacement clip for broken or missing OEM clips
Recomended Tools:	
84754-TL5	TCC apply valve reamer and drill jigs

©2003 Sonnax° SC-4T60E (rb) 12/03/03