
PART NUMBER 63741-05K

# **TCC Control Sleeve Assembly**

### 63741-05K

- 1 Plunger Valve
- 1 Plunger Sleeve

**Note:** Fits Nissan, Infinity RE5R05A and Kia A5SR1/A5SR2.



#### **Disassembly Steps**

- 1. Remove OEM sleeve and plunger valve assembly and discard.
- 2. Keep OEM retainer for re-use.

## **Installation Steps**

- 1. Insert replacement sleeve/valve assembly into bore, open end first.
- 2. Make sure OEM spring fits over reduced sleeve diameter.
- 3. Push into bore far enough to reinstall OEM retainer.

## **Final Verification Steps**

Vacuum testing at the orificed converter apply port should yeild 18" of vacuum or higher.

