You asked for U151E/F, U250E Solutions, Sonnax Developed Them

1. 57917E-19K* 3 Locations

Accumulator Piston Kit

Helps cure:

- Delayed engagements
- Slipping/flares in forward gears
- Burned clutches

2. 57917E-16K*



Oversized Secondary Pressure Regulator Valve Kit

Helps cure:

- Harsh lockup
- Converter apply/release complaints FIXTURE
- Burned converters

Note: Requires tool kit F-57917E-TL16 & the VB-FIX reaming fixture.

3. 57917E-03K*


Lockup Control Plunger Valve & Sleeve Kit


Helps cure:

- TCC apply/release problems
- Converter codes
- Burned converters

4. 27741-13K Solenoid Modulator Valve Kit

Helps cure:





• Loss of cooler flow/overheating

Note: Requires tool kit F-27741-TL13 & the VB-FIX reaming fixture.

5. 27741-06K

B2 Apply Control Plunger Kit

Helps cure:

- Burned B2 brake/clutch
- Delayed reverse
- Loss of engine braking in manual low



B1 Apply Control Plunger

Helps cure:

- Burned B1 brake/clutch
- 2-3 or 4-3 bind-up condition
- Harsh 1 through 4 maneuver shifts



7. 27741-01K

Boost Valve Assembly

Helps cure:

- Insufficient line rise in drive ranges
- Higher than normal reverse pressures
- Soft shifts

27741-08K

Oversized **Pressure Regulator & Boost Valve Kit**

Helps cure:

- Low/high line pressure
- Soft and/or harsh shifts
- Clutch and band failures

Note: Requires tool kit 57917E-TL8. This tool kit is also used to install 57917E-08K for Toyota U140E/F, U240E & U241E



*Note: These kits also fit the Toyota



Automatic Drive • P.O. Box 440 • Bellows Falls, Vermont 05101-0440 USA 800-843-2600 • 802-463-9722 • F: 802-463-4059 • www.sonnax.com • info@sonnax.com