(0

0

Relief Valves

small parts program

Benefits:

- Works with existing spring
- No modifications needed

Part No. 10000-01K

10 Relief valves

Part No. 10000-02K

10 Relief valves









PART SUMMARY

Sonnax now offers replacements 10000-01K and 10000-02K for the various relief valves and drainback valves that are found in valve bodies. The design of the OEM valves causes the separator plate and valve bore to wear. The result is leakage or valve sticking. The Sonnax valve is rounded so it seals against an unworn part of the separator plate and eliminates sticking problems.



The Sonnax valve is ideally suited for replacing the drainback valve on AXOD, AXOD-E, AX4N and AX4S units. The OEM drainback valve frequently sticks in the bore. A common shop practice is to replace the OEM drainback valve with a check ball. However, this practice requires shortening the spring. The Sonnax valve solves the sticking problem and is designed to work with the existing spring. No spring modifications are needed.

Although either part number can be used in multiple locations, it is suggested to use a relief with a radius close to original, maintaining the spring rate. On a severely worn plate or bore, the higher radius will allow for better plate contact and less bore hang-up.

©2001 Sonnax 10000-01K & -02K(info)6-15-01