
PART NUMBER 95200-01

Line Pressure Regulator Valve Cushion Spring

95200-01

1 Cushion Spring



Installation Instructions

- 1. Remove boost-valve sleeve retainer, sleeve, line control plunger, spring guide, pressure regulator valve spring and the broken orange cushion spring.
- 2. Discard the broken spring and install Sonnax's improved "orange" cushion spring 95200-01.
- 3. Reassemble with all remaining OEM parts.

Notes:

- Also inspect the bore for wear at the pressure regulator valve.
- Conditions related to bore wear are harsh shifts, delay or no reverse.

