Part No. SC-AXODE

AXODE



FROM

sonnax

onnax Sure Cure® Kits Combine "the best" Sonnax products into one box, offering rebuilders a convenient and cost-effective way to address common transmission problems. These kits simplify ordering, stocking and estimating job costs, and include easy-to-read, step-by-step instructions that cover the inspection and repair of the most critical areas of the unit, and even a reference list of rebuilding specifications.



This AXODE transmission reconditioning kit includes the following Sonnax parts and addresses these problems:

·	
Sonnax Part	The SureCure® for:
Boost valve assembly (96201-01K)	2-1 downshift clunk, harsh reverse, poor line rise
 Bypass clutch control valve assembly (96206-01K) 	Code 628, TCC apply/release problems, lube failures
Forward control valve kit (96201-16K)	Slippage in or no forward and reverse
• 3-2 shift timing valve saver kit (96201-15K)	Neutral on 3-2 downshift, damaged valve and clip
Rear ring gear retaining ring (96730-RR)	No movement caused by OEM ring popping out of groove
Servo pin split-ring retainer (96945R)	OEM clip breakage. <u>Highlight:</u> Split ring designed retainer will not break
Servo tube retaining bracket (96803)	No forward or 3rd gear by holding in loose servo tubes
 Valve body retainer clips (96201-10, 96201-11) 	Broken or missing OEM retainers
TV cable corrector kit (AS1-01K)	Throttle cable being pulled out of adjustment at wide open throttle
 Pump shaft lube plug (96855-04K) 	Poor lube, dirty shafts
Recommended Tools:	
96201-BST	Bore sizing tool for forward control valve

