CHRYSLER RWD ('78-UP W/TCC)

Part Number 22771A-02K


Lube Regulated Pressure Regulator Valve

22771A-02K


1 Pressure Regulator Valve

Note: U.S. Patent No. 6,712,726

Note: To prevent converter slippage, restricted cooler flow and possible hydraulic noise, remove the cooler line drainback valve.



Valve Body Inspection



- 1. If a line-to-lube hole has been drilled in the PR valve circuit, it should be plugged to reduce converter drainback.
- 2. Inspect the line pressure plug and sleeve. Leakage here will result in poor line pressure control.
- 3. Inspect the TV checkball separator plate seat. Leakage here may produce stacked shifts and or no kickdown.




CHRYSLER RWD ('78-UP W/TCC)

Part Number 22771A-02K

Installation Instructions

1. Remove the detent assembly and spring retainer bracket (see Figure 1).



- 2. Remove the original pressure regulator valve and replace with Sonnax valve 22771-02K.
- 3. Adjust the pressure regulation spring for correct line pressure (see Figure 2).

Important: Line pressure should be set to 65-70 psi at idle with minimum TV.

4. Line pressure should be verified with a gauge after installation (pressure tap on passenger side, middle of case, between accumulators).

Important: Line pressure in excess of 80 psi may cause binding due to cross leaks and excessive throttle sensitivity.

Note: To prevent converter slippage, restricted cooler flow and possible hydraulic noise, remove the cooler line drainback valve.

Figure 2

